



Newsletter

September 2026

Dear students, parents and employees in the school, KKFO, after school club, dental care clinic and library

In May 2026, we informed you about the rearrangements of the rehousing during the planned renovation of Ørestad School. The entire school now needs to be rehoused, partly because more extensive work needs to be done inside the building than previously expected. This newsletter focuses on the upcoming rehousing.

Larger rehousing at Arne Jacobsens Allé

Previously we planned to temporarily rehouse half of the school at a pavilion school at Arne Jacobsens Allé 6. We are now planning to expand this rehousing solution, so the school, KKFO, and the after-school club can stay together. Pavilions with outdoor areas still need to be set up for the school. On the other part of the site, pavilions are currently being constructed, which will initially be used for temporary daycare institutions.

It is our expectation that the daycare institutions can move to permanent locations in the first half of 2029.

To make room for the rest of the school, we are planning to convert the pavilions and the associated playgrounds for school use, including general classrooms and relevant subject-specific rooms.

The oldest students will still have their classes in Mediebyen, and we will also keep subject-specific rooms in HUB 1.

At this point, we assess that the library and the dental clinic can remain open during the renovation project, possibly with a brief closure. We also expect that the indoor sports hall can be used to a large extent throughout the renovation project.

The renovation starts in 2029

We have previously announced that the renovation project would begin at the earliest in the summer of 2028. The new situation means that we now expect the renovation to begin in 2029.

By rehousing the entire school, the renovation can be completed more quickly than if the renovation had to take place while school activities continued in the building. We expect that the renovation can be completed in about two years instead of three.

We will continue our rehousing planning in close cooperation with the school, the after-school club, and others.

Kind regards,

Byggeri København

Reasons to renovate Ørestad Skole

Ørestad Skole will be going through a renovation as, unfortunately, there are various problems with the building.

These include leaky roofs and external walls, cracked and leaky windows, and the fact that the so-called wind barrier plates that sit behind the bricks cause the metal structures behind the bricks to rust. Therefore, among other things, the wind barrier panels must be removed and the outer side of the outer walls replaced, leaky and cracked windows must be replaced, and the roof must be sealed.

Furthermore, there is also a need to strengthen the building. This is necessary to fulfill the requirements in the Building Regulation. The strengthening of the building is intended to prevent future damage to the building such as cracks, that must be fixed on an ongoing basis. There is no risk in being in the building.

If you have any questions about the project, you can contact us via the link or the QR code.

<https://byk.kk.dk/om-os/kontakt>

